# Trimble 4000 series - How to replace internal batteries

333 Jim Normandeau December 11, 2009 Application Notes 4774

The attached .pdf file contains information on replacing the internal batteries in a 4000SSe/SSi GPS receiver.

Online URL:
https://kb.unavco.org/article/trimble-4000-series-how-to-replace-internal-batteries-333.html