


## UNAVCO Fixed-height 0.50m Spike Mount (not recommended) (diagram)

315 Beth Bartel March 24, 2010 [UNAVCO Fixed-height Spike Mount](#) 668

### UNAVCO Fixed-height 0.50m Spike Mount



Note that this spike mount is not recommended due to the antenna's susceptibility to multipath at this height.

Online URL:

<https://kb.unavco.org/article/unavco-fixed-height-0-50m-spike-mount-not-recommended-diagram-315.html>